Oil Field Environmental Incident Summary

Responsible Party: QEP ENERGY COMPANY **Well Operator:** QEP ENERGY COMPANY

Well Name: OTIS 3-28-33BH

Field Name: GRAIL Well File #: 26847

Date Incident: 12/9/2015 Time Incident: 06:00 Facility ID Number:

County: MCKENZIE Twp: 150 Rng: 95 Sec: 21 Qtr: SE SW

Location Description:

Submitted By: Jerry Reinisch Received By:

Contact Person: Jerry Reinisch

1050 17TH ST STE 500 DENVER, CO 80265

General Land Use: Pasture Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1.6 MileDistance Nearest Water Well:0.9 Mile

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 10 Barrels 10 Barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

flammability low as related to produced water. Spill was contained on the pad location.

Areal Extent:

Potential Environmental Impacts:

Scoria around water skid impacted

Action Taken or Planned:

Liquids sucked up and replaced in system. Impacted scoria removed from location and hauled to an approved disposal site.

Seals and pumps will be checked more frequently.

Wastes Disposal Location: At an approved disposal site. Crews are working to clean-up the spill at

the time of report.

Agencies Involved:

Updates

Date: 12/10/2015 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, remained on constructed well site according to the report. NDIC retains oversight.